

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



FIG 1
Top view






FIG 2

END VIEW




FIG 4A




FIG 4B



FIG 4C

Comparative Field Strength Along Center of Erosion




Figure 5.




FIG 6 A
PRIOR ART




FIG 6 B




FIG 7A
PRIOR ART




FIG 7B




Fig 8




FIG 9




FIG 10

Aluminum thickness profile top-to-bottom LMM cathode version 3




Figure 11.

Aluminum oxide thickness profile top-to-bottom LMM cathode version 3




Figure 12.

Aluminum Oxide Hysteresis Loop for LMM Cathode




Figure 13




Figure 14 a. Theoretical simulation of oxide film step coverage achieved by prior art.




Figure 14b.